MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 47 NR 17 W

				. A.I.& Q	*		COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	between Seal	ions 16 a	nd 21	
DESCRIPTION	OF	CORNER	MONUMENT	2º Iron Pi	be aiff §#	Brass Car	2
WITNESSES	то	CORNER .	6" Soft May	10 (1/40 E	et) n_	78° W _ 22	1/2 [4nks
			10° Klm	(1/4e_)U	r) i	35° E _ 34	Links
				- -		- - - -	
						_	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-witnessed. Pipe with Brass Cap set by unknown party checks fairly well with being in line and prop. distance between section corners.

Corner was placed and witnessed August 17, 1960.

SURVEYORS SEAL

SIGNED Suchles

REGISTERED LAND SURVEYOR

Billy D. Buckler