

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47.. NR. 17.. W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 31 and 32

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (1/4" NBT) N 30° E 27 1/2 Links

10" Cedar (1/4" NBT) S 32° E 28 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from down Tamarack marked with Crayon (BT)

(no visible iron marks) down Cedar with Iron Mark visible in poor condition.

Cedar 7" S 63° E 6 Links, Tamarack 8" N 66° W 5 Links. Corner found by Ken Killmar.

Corner was placed and witnessed August 3, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 8/12/60