

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Alger</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S 16 T 47N R 17W	2
	S 16 T 47N R 17W	9
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						

Aug 08 2006

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (2-Sec. 16) East 1/16 corner between Sections 9 and 16. Not established in the original survey.
- (9-Sec. 16) East 1/16 corner, Section 16. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (2-Sec. 16) Established the corner midway and on the Section line between Quarter corner 1320.54' west and Section corner 1320.54' east.
- (9-Sec. 16) Established the corner midway and on a straight line between intersection of 1/4 lines 1328.96' west and Quarter corner 66 1328.96' east. The position for the corner falls in a limestone drainage.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--|--|
| (2) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap. Set measuring nails in:
5" Maple N03E 21.1' mrkd "E1/16 BT"
5" Cedar N54E 44.5' do
5" Maple S46E 31.2' do
5" Maple S05W 19.3' do
Bearings are magnetic. Distances are to
nail with tag. | (9) Set 1"IDx36" I.pipe with 4" alum.
MDNR cap cemented into a mound of
limestone rock. Set measuring nails in:
5" Maple S81E 19.3' mrkd "E1/16 BT"
8" Maple N57E 25.6' do
5" Ironwood N76W 20.55' do
5" Cherry S74W 18.7' do
Bearings are magnetic. Distances are to
nail with tag. |
|--|--|



Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 12/12/06

For the Michigan Department of Natural Resources, Office of Land and Facilities