LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ALGER		Located In:		Corner Code ≠#
1	Public Land Survey		T Rii	
			T R	
			T. R T R	
2	Property Controlling	S 29	T .47N F .19W	1
	in Section	s 29	T 47N R 19W	3
3	Miscellaneous	S	T R	

Register of Deeds Stamp & File Number

4 Lot No . Recorded Plat

5 Private Claims

Property in Sec.

I. Gerald. L. Wiggins in a field survey on $\frac{1-31}{1000}$, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A Description of original monument and accessories and/or subsequent restoration:
- West 1/16 Corner on North side of Section 29. Not previously set.
- North 1/16 Corner on West side of Section 29. Not previously set.
- B Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner set due east and record distance, 1320' from the N.W. Corner of Section 29.
- Corner set midpoint on line between West 1/4 Corner and N.W. Section Corner of Section 29.

- C Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1" Pipe with plastic R.L.S. Cap set at both corners.
- 1 10" Maple, N56°W, 16.5' 4" Maple, N28°W, 15.3'
 - 10" Maple, East, 23.3'
 - 8" Maple, South, 28.1'

- 3 14" W.Pine, S61°W, 6.85' 10" W.Pine, N85°W, 4.15'

 - 10" Balsam, S63°E, 2.55'
 - 8" Spruce, S15°W, 4.2'

