Approve	d by Alge	r County
Land Surve	v Remon	umentation
Peer Grou P.A. of 1990	p Under	Aet 345 of
P.A. 01 1990		Z_19 <u>ZZ</u>

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4-271

For corners in	Filing Requir	rement of Act 74, Mich. F	P.A. 1970 FiLED
Alger (County)	_ Located In:	Corner Code ##	TIME 2:35 p.m.
1. Public Land Survey	T <u>47N</u> R <u>22H</u> T R T R	_H4	NOV 17 1994 DONALD W. KINNUNEN
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R		REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Rec. 5. Private Claims i,	in a field survey on	y 10, 1993 , 19 , 19 , 19 , 19 , 19 , 19 , 1	2 6 5 4 3 2 3 4 7 8 9 11 12 5 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 15 15 15 15 15 15 15 15 15 15 15 15
A. Description of original mo			13 13 13 13 13 15 15 15 15 15 15 15 15 15 15 15 15 15

H4: Methods to be applied in establishing this corner position were part of instructions to Deputy Surveyors during the Public Land Surveys. Monuments were not installed at that time. Geo.L. Depen, CS, 1918. Center post established on true line East-West and North-South. Alger County Road Comm., H.H. Anderson, CE, 1935. Found iron at road station 42+53.2 as part of road alignment and construction of Deerton Road. Alger County Road Comm., E.Swan, RLS, 1946. Found 1"steel pin at road station 35+65.9 (Labled Center Post) as part of road alignment and construction of Deerton Road. Gerald W.Carlson, RLS, 1977. Set 5/8" x 18" iron m/RLS cap at distances compiled from road stations and alignment information as given on 1935 and 1946 Alger County Road Comm. plans. Established references, 6" Balsam, S.79 W., 66.54 ft., 12" White Birch, N.50 W., 49.60 ft., 10" White Birch, N.24 W., 91.82 ft. Recording No's. 115 and 278, Alger County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H4: Found 5/8° Rebar M/R.L.S. cap, identified by references on record report, 3 feet west of the centerline of Deerton Road and on centerline of gravel road to the west. Rebar set by Gerald W. Carlson, R.L.S. with reference to maps from Alger County Road Commission files. Recorded in filing No. 278 & 115 Alger County Records. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

C_{H4}: Description of monument for corner and accessories established to perpetuate locating the position of the corner: 114: Installed 3 1/4 Alum, cap on

existing 5/8" Rebar, stamped to I.O. Corner. Est. reference trees w/BT signs, blazed, scribed and painted. Set PK nails for measuring w/brass I.D. washers in the following reference trees. Power Pole No. B68, N.83 E., 35.39 feet, "BT". W. PIne 7", S.51 W., 43.32 feet, "C1/4-BT". Ex. W. Birch 14", N.52 W., 50.0 feet, "BT". Maple 4", N.29 W., 75.65 feet, "C1/4-BT").

10 duly, 1994

Date