Approved by Alger Cour	nty		•
Land Survey Remonument Peer Group Under Act 34 P.A. of 1990 On 27 19	15 of ,,		
Matrali	,	ER RECORDATION CER	TIEICATE
ZHING Chairman		ement of Act 74, Mich.	
For corners in	Thing require	ement of Act 74, mion.	4-259
Alger (County)	Located In:	Corner Code ##	
(OODRY)			FiLED
1. Public Land Survey	T <u>47N</u> R <u>22H</u>	_H5	TIME 2:35p.m.
	T R T R		
	T R		NOV 17 1994
2. Property Controlling	S T R		
in Section 3. Miscellaneous	S T R		DONALD W. KINNUNEN
Property in Sec.	S T R S T R		Register of perds ship & Pike Number
	ecorded Plat		
5. Private Claims	······································		2 6 5 4 4 3 2 1
			3
			4 7 8 9 10 11 12
	in a field survey onJune		
	uirements of P.A. 74, Michigan P.A. conformance with regulations an		
current manual of survey instru-	ctions of the United States Depart	tment of the Interior, Bureau o	of Land 7
-	i Court of Law and/or that the corne h the rules of the Michigan Board o	•	ree of a
Court of Law; established, re	e-established, monumented, re-r	•	und as
expressed below:			10 30 29 28 27 26 25
on this certificate.	orners, all in the same town ar	ng range, may be recorder	12 31 32 33 34 35 36
			13 3 3 3 3 3 3
 A. Description of original m 	nonument and accessories and	d/or subsequent restoration	on:
construction of Deerton Roa	ad. Gerald W. Carlson, RLS, 197 ences, Power pole, S.45 E., 45.	77. Found 11/2° solid axle	Station 63+66.56 as part of road alignment and in center of road, in line with north edge of road 49.90 ft., 7° Spruce, S.73 E., 45.54 ft. Recorded
B. Description of corner ev	ridence found and/or method a	applied in restoring or rees	stablishing corner:
·			st of centerline of the Deerton Road, 8.0 feet north
of centerline of gravel roa evidence of Sugar and Y. Bi existing 11/2" solid iron a monument at corner position	ad west and on centerline of wo irch, inconclusive. Road and p and checked position with locat	oods road east. A search wa powerline construction has cor. Received a positive in ld iron. Corner position ha	s made at the original BT locations for remaining destroyed remaining evidence. Witnessed and removed dication of the existing buried monument. Placed news a long standing history in area and is accepted as
C. Description of monumen H5: Set 5/8" x 18" Redar #	it for corner and accessories e 1/3 1/4" Alum.	established to perpetuate i	locating the position of the corner:
cap, stamped to I.D. corner			
reference trees w/BT signs, scribed and painted. Set P			
measuring w/brass I.D. wash			
following reference trees.			
N.61 W., 43.48 feet, "BT".			
5", N.74 E., 50.0 feet, "BT Pole No. 203, S.48 E., 45.7			
Ex. Spruce 8" (dead) \$.75 E	-		
Telephone Pedestal No. 21,			
feet.	1/1/1/1	•	
Signed by	Telet Deta	muls Date	10 duly, 1994
Surveyor's Michigan License	No 25849		/ ' .
sarveyor a micingan Electise			FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983