SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of

JUL 3 0 1995

A. 01 1930 On 3/6	COMMISSION
Guald Worson	COMMISSION LAND CORNER RECORDATION CER
Chairman	Filing Requirement of Act 74, Mich.

4-375

<u></u>	Filing Requi	rement of Act 74, Mich. P.A	. 1910
For corners in Alger	Located In:	Corner Code #	FILED
(County)			TIME 3:00 p.m.
1. Public Land Survey	T 48N	-	JUN 27 1996 DONALD W. KINNUNEN
2. Property Controlling in Section3. Miscellaneous	ST R ST R ST R		REGISTER OF DEEDS ALGER COUNTY, MI
Property in Section	ST R	<u> </u>	Register of Deeds Stamp & File Number
,Robert L. Jamros do hereby certify that under in lines 1 and 2 above were	, in a field survey onFet requirements of P.A. 74, Michigan in conformance with regulations and	oruary 15, 1996 , 19	2 6 5 4 3 2 4 7 8 9 10 11 12 5 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 13 6 15 14 15 14 15 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
Management or by a decree 5 above were in conformar Decree of a Court of Law; as expressed below:	e of a Court of Law and/or that the nee with the rules of the Michigan established, re-established, monum corners, all in the same town as	corner points mentioned in lines 3, Board of Professional Surveyors or ented, re-monumented, recovered,	4 and 8 19 20 21 22 23 24 r by a

A. Description of original monument and accessories and/or subsequent restoration:

B9: PLS-George E. Adair, DS, 1851, Set Qr. section post - Beech 10", N.27 1/2 W., 10 links, Maple 8", S.42 1/2 E., 18 links.**** Ray J. Brotherton, RLS, 1950, Set iron R/R rail from government beech bearing tree in Northwest location. As noted in leather bound books of GLO field notes, Page 91, T.48N., R.15W., Alger County Records. No references given. No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B9: Found small guage vertical railroad rail and three inch squared top picket at corner position. At GLO BT location found 22 ' dead beech stub eight feet high, N.27 1/2 W., 6.6 feet (10 links), with blazes and inside rotted away. Found two existing bearing trees standing and healthy, Believed to be set by Ray J. Brotherton. Renewed existing witnesses to current Alger County standards and established additional reference trees. Set monument at this position on north side of railroad rail. Rail was set from original bearing tree location and is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B9: Installed Berntsen Mon. No. A1NB30 along north side of railroad rail, Stamped to identify corner position. Established reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Maple 12", S.22 E., 23.74 feet, " Obl. Blzd.", Ex. Maple 8", N.64 E., 9.32 feet, " Obl. Blzd.", Ex. Maple 9", N.29 W., 15.84 feet, " Obl. Blzd.", Maple 8", S.68 W., 26.51 feet, " 1/4s BT ", Survey marker sign on six foot steel post, S.67 E., 1.0 feet. All bearings are magnetic.

Signed by_

25/19/9

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ROBERT L. JAMROS PROFESSIONAL SURVEYOR No.

Surveyor's Michigan License No.