## REMONUMENTATION

FEB 2 3 1999

Approved by Alger County

Peer Group Under Act 345 of	SI	ECTION	
P.A. of 1990 On 416 1998  Chairman		ER RECORDATION CERTI	<u> </u>
For corners in			
Alger (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>48N R15W</u>	<u>E 4</u>	TIME 10:00 A.M.
	TR TR TR		JAM 8 1999
2. Property Controlling S in Section S	TR TR		DONALD W. KINNUNEN REGISTER OF DEEDS
3. Miscellaneous S	TR TR		ALGER COUNTY, Mf Register of Deeds Stamp & File Numbe
4. Lot No, Recorded F			ABCDEFGHIJKL
5. Private Claims			$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
		,	3
I Pohert I lamme in a	field curvey on light?	20 10 08 do her	4 7 8 - 9 10 11 12 12
1, <u>Robert L Jamros</u> , in a field survey on <u>July 30</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual			<b>s</b> 1
of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in			t or 7
conformance with the rules of the Michi established, re-established, monumented	igan Board of Land Survey	ors or by a Decree of a Court of L	aw, 8 19 20 21 22 23 24
NOTE: Not more than 2 corners,			10 30 29 28 27 26 25
on this certificate.	an III uic Saire wwii air	u lange, may be recorded	11
			12 - 31 - 32 - 33 - 34 - 35 - 36
A. Description of original monum	nent and accessories a	ind/or subsequent restoration:	13
standing Beech BT. R.J. Br * Robert E. Schmeling obse following. * Beech 18", due 25.3 feet (1/4 S9 NBT) * Bee	rotherton installed an a erved the original evider North, 23.5 feet (1/4 S ech 10", S.18°W., 11.3	xle shaft and made a new bea nce and replace axle shaft witl 9 NBT) * Beech 12*, N.20°E.,	orded) from a Hemlock BT stump and a ring tree, Beech 12", N.30°W., 27 ½ links. 1" G.I.P. with brass cap and established the 22.2 feet (1/4 S9 NBT) * Beech 20", S.59°E., ed cedar post with aluminum locator tag. *
•		d applied in restoring or reesta	•
and accessories in good cor Northwest position and Hem	ndition and in acceptab	ole location. Osberved the follow note in Southeast position. Als	rement. Found monument of the 1980 report owing evidence of GLO, decayed stump in to R.J. Brotherton BT, Beech 16" stump, expetuation of the position of the original corner.
C. Description of monument	for comer and accesso	ories established to perpetuate	locating the position of the corner:
aluminum I.D. washers in the	he following. * Existing 24.67 feet. * Existing -	- Beech 22", N.04°E., 23.20 fe	ns and paint. Set PK nails for measure with eet. * Existing - Beech 15", N.18°E., 22.00 et. * Survey marker sign on 6 foot steel post,
			٠,
$\alpha$			
Signed by Signed	ut of lam	143_	Date December 16, 1998
Surveyor's Michigan License No.	258	49	
' <b>,</b>	ET TO THE REAL PROPERTY OF THE PERTY OF THE	S ECON ADDOCA	D BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28
	ROBERT L.  JAMROS  PROFESSIONAL  SURVEYOR	TAGE ATTROVE	DBY MICHIGAN STATE BURNEY OF PROFESSIONAL SURVETONS, SALE 20 REVISED MAY 1 REVISED JAN, REVISED OCT