REMONUMENTATION

FEB 1 9 1998

Approved by Amer County
Land Survey Resonance of a
Peer Group brase / American
P.A. of 1980 On 12-10: 47

SECTION

05-48

LAND CORNED BECORDATION CERTIFIC

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 FILED For corners in Corner Code # Located In: 8:30 A.M. TIME_ (County) 15 48 1. Public Land Survey <u>-:5₩</u> R <u>- :5₩</u> DEC 17 1997 ___ R __ DONALD W. KINNUNEN R Т REGISTER OF DEEDS Т R ALGER COUNTY, MI 2. Property Controlling S Т __ R _ R in Section S Т Т Miscellaneous Register of Deeds Stamp & File Number Property in Section _, Recorded Plat 4. Lot No. 5. Private Claims _ _, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

IS: PLS - George E. Adair, DS, 1851 * Set quarter section post * White Pine 8, N.65 = ..., 11 links * White Pine 13, S.66 E., 25 links ***** Dean C. DeLaMater, RLS, Michigan Department of Conservation, 1951 * Corner found while making partial resurvey of this township * Corner previously located and perpetuated by R.J. Brotherton, RLS * Replaced exist. monument w/1 inch galv. Iron pipe w/4 inch brass cap * Witness's - White Pine stump 40, 5.30 E., 97 links * White Pine stump 32, 5.70 H., 94 links * Recorded in Liber 2, Page 4, Alger County records. ***** No other subsequent restoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

IS: Found 1 inch galv. From pipe withass cap and truck spring leaf * Corner position 1/2 mile North also had a truck spring leaf for a monument. * Recovered BT's of the 1951 recorded report * Measurements to adjacent corners check very well. * Renewed existing BT's and established additional reference trees * Monument position as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

IS: Exist. 1 inch galv. iron pipe w/brass cap as stamped to identify the corner position * Renewed exist. BT's w/BT signs and paint * Established additional reference objects w/BT signs, scribed and painted * Set PK hails w/Alum. I.D. washers for measure in the following - Exist. BT, White Pine stump 40, S.20 E., 64.19 feet, scribing visible * Exist. BT White Pine stump 32, S.71 W., 61.87 feet, scribing visible * White Pine stump 33, S.71 W., 61.87 feet, "BT" * Survey marker sign on 6 foot steel post, N.05 W., 1.1 feet * All bearings are magnetic.

Signed by Alut Scanuse
Surveyor's Michigan License No. 25849

JAMROS
PROFESCIONAL
SURVEYOR
Date /Z/105/X997 No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

ROBERT L

EVISED MAY 14, 1975 REVISED JAN 1983