Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 3-24 1997

4	lD	Carlson			
Ghairman					

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

5-33

ALGER	Located In:	Corner Code #	
(County)			FILED
Public Land Survey	T R 15W T R	<u>K4</u>	TIME _ 2:00 pm.
	T R T R		MAR 3 1 1997
Property Controlling     in Section	S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS
3. Miscellaneous	S T R		ALGER COUNTY, MI
Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No, 5. Private Claims	Recorded Plat		A B C D E F G H J K L N  2 6 5 4 3 2 10 11 0 12
do hereby certify that under re in lines 1 and 2 above were in manual of survey instruction Management or by a decree of 5 above were in conformance	conformance with regulations and rul ns of the United States Department of a Court of Law and/or that the corr on with the rules of the Michigan Boa	of 1970, the corner points mentioned es therefore as required in the current nt of the Interior, Bureau of Land ner points mentioned in lines 3, 4 and rd of Professional Surveyors or by a d, re-monumented, recovered, found	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 12 31 32 33 34 35 36 36 36 36 36 36 36 36 36 36 36 36 36

Description of original monument and accessories and/or subsequent restoration:

K4: PLS - George E. Adair, DS, 1851, Set quarter Section post \* Y.Birch 8, N.31 W., 22 links \* Beech 11, S.70 E., 23 links \*\*\*\*\* Ray J. Brotherton, RLS, 1949. \* Set iron and post from original Y. Birch BT, N.31 W., 22 links. \* Witness, Sugar 3', N.50 W., 23 links. \* Sugar 12\*, S.47 E., 38 links. \* C.C.I.Co. Records. \*\*\*\*\* I.J. McClaren, C.C.I.Co., 1967. \* Found post set by Ray J. Brotherton and two reference trees. \* C.C.I.Records. \*\*\*\*\* Robert E. Schmeling, RLS, 1980. \* Found decayed post on ground, recovered point. \* Also found 1949 reference trees, Sugar 8°, N.50 W., 23 links and Sugar 16°, S.47 E., 38 links. ★ Set at recovered point location a 1° diam. 4 foot long galvanized iron pipe with brass cap stamped to identify corner position. \* Witness, Hard Maple 14', N.35 E., 24.7 feet, scribed. \* Hard Maple 11", 5.34 E., 38.5 feet, scribed. \* Beech 11", S.41 W., 34.5 feet, scribed. \* Hemlock 8", N.20 W., 26.6 feet, scribed. \* Recorded in L.1, P. 362, Alger County Records. \* No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K4: Located existing 1° diam. galvanized iron pipe with brass cap and two existing BT's, 1949 unrecorded report. \* Sugar 3', N.50 W., 23 links and Sugar 12", S.47 E., 38 links. \* Also found four existing BT's from 1980 report, with one being a dead stub. Beech 11", S.41 W., 34.5 feet. \* Remains of GLO BT Y.Birch 8°, (now stump) quite evident, N.31 W., 22 links. \* Monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K4: Stamped P.A. 345 in the existing brass capped monument. Renewed three existing reference trees w/ BI signs and paint. Established additional reference tree w/ BT signs, blazed, scribed and painted. Set Pk nails for measure w/ Alum. I.D. washers in the following reference trees. \* Exist. BT, Hemlock 12", N.19 W., 26.31 feet, marks visible. \* Exist. BT, Maple 20", N.35 E., 24.38 feet, marks visible. \* Maple 20', 5.33 E., 24.38 feet, marks visible. \* Maple 7', 5.17 W., 24.85 feet, '1/48 BT'. \* Survey marker sign on six foot. steel post, N.55 W., 1.5 feet. \* All bearings are magnetic.

Signed by

Surveyor's Midhigan License No.

ROBERT L.

25489

PROFESSIONAL.

No.

25849 OFESSION

SURVEYOR

JAMROS.

1997 March

ROYED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983