MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_45_ NR_15_W_

		COUNTY
DESCRIPTION	OF CORNER	1/4 Corner between Sections 17 & 18
DESCRIPTION	OF CORNER	MONUMENT_IN Pipe with An Brass cap
WIT TNESSES	TO CORNER	32" W. Pine Stub - N 59 W - 79 Links
		20" W. Pine Stub - N 61 E - 34 Links
	,	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by preportionate measurement, by Forestry Division survey crew; while making a partial resurvey of this Tewnship. Line Tree, good condition, 8 Chains North.

Cerner was placed and witnessed Nevember 3, 1952.

SURVEYORS SEAL

SIGNED LEW _ _ _ DATE 2/26/59