MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_48 NR_45 V.

			<i></i>	- COUNTY
DESCRIPTION	OF	CORNER	Section Corpor comen to Sections 9,10,15,	<u>r</u> 6
DESCRIPTION	OF	CORNER	MONUMENT_IT Pipe with 4" Press cap	
WITTNESSES	то	CORNER	_ 12" T. Pine = N 64 V = 407 Links	
			_ 14" N. Pine = N 4 E = 3% Links	
				-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by E. C. Hall, District Forester, of Shingleton. Two original B.T.'s in place, badly burned. Corner had been previously located and perpetuated by R. J. Brotherton, Registered Land Surveyor, of Munising.

Corner was placed and witnessed July 19, 1951.

SURVEYORS SEAL

SIGNED LEAN SURVEYOR DATE 7/16/51