

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 48. NR. 15. . . W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 9 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 14" W. Pine Stump (1/4s NBT) . . N 70° W . . 65 Links

36" W. Pine Stump (1/4s NBT) . . N 35° E . . 70 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section corners. No evidence of original corner.

Corner was placed and witnessed June 22, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Backler DATE 7/27/60
REGISTERED LAND SURVEYOR
Billy D. Backler