

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



LAND CORNER RECORD

T. 48 .. NR. 15 .. W

.. A l g e r .. COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 3 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 1 1/4" Beech (1/4s NBT) N 40° E 45 Links

1 1/4" Beech (1/4s NBT) S 36° E 25 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section corners. Found old blazes in vicinity of corner. Corner lies 40 links west of road,

Corner was placed and witnessed June 22, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/27/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler