

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 48. NR. 15. . . W

Alger . . . . . COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 4 and 9 . . . . .

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap . . . . .

WITNESSES TO CORNER 12" Red Pine (1/4s NBT) S 2° E 170 Links . . . . .

13" W. Pipe (NBT) S 56° E 75 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section corners. No evidence of original corner.

Corner was placed and witnessed June 22, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/27/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler