

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 NR. 15 W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 27 and 28

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" W. Pine (1/4s NBT) N 82° E 13 1/2 Links

12" Hemlock (1/4s NBT) S 72° W 19 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section corners. No evidence of original corner.

Corner was placed and witnessed June 23, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 7/27/60