

Approved by Alger County Land Survey Hemonumentation Paer Group Under Act 345 of

FEB 1 9 1998

	1930 On		
И		1) Car	Pron -

SECTION

05-91

Guslow Calson	LAND CORNER RECORDATION CERTIFICATE
Chairman	Filing Requirement of Act 74, Mich. P.A. 1970

(County)	Located In:	Corner Code #	F.LID
Public Land Survey	48 16 T <u>:</u> N R ::-	FII	TIME _ 8130 A.M.
T. Tubilo Land Galvey	T R T R		DEC 17 1997
 Property Controlling in Section Miscellaneous Property in Section 	T R S T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY, M! Register of Deeds Stamp & File Number
	ecorded Plat		2 6 5 4 3 2 1 1 3 X L M
do hereby certify that under require lines 1 and 2 above were in commanual of survey instructions Management or by a decree of 5 above were in conformance.	in a field survey onuirements of P.A. 74, Michigan P.A. onformance with regulations and rule of the United States Departmental a Court of Law and/or that the conwith the rules of the Michigan Boablished, re-established, monumental	of 1970, the corner points mention les therefore as required in the curr ent of the Interior, Bureau of La ner points mentioned in lines 3, 4 a ard of Professional Surveyors or b	ned 6 18 17 18 15 14 13 rent 7 and 8 19 20 21 22 23 24 by a gund 10 30 29 28 27 26 25
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town and i	range, may be recorded	11
A. Description of original r	monument and accessories an	d/or subsequent restoration:	
Fil: PLS - William Ives, D	S, 1850 = Set quarter post * S	ugar 5, S.55 W., 19 links * So	ugar 7, N.10, W., 22 links ***** P.J. Eretherton,

Fil: PLS - William Ives, BS, 1850 * Set quarter post * Sugar 5, S.55 W., 19 links * Sugar 7, N.10, W., 22 links ***** P.J. Bratherton, RLS, 1948 * Set 3 inch iron spring leaf * Government Sugar BT here, N.10 W., 22 links, good shape * stump only on the Government BT, S.55 W., 19 links * Iron is flash worseks packed around top * Witnesses - Maple 3, S.15 W., 34.6 feet * Maple 8, N.05 W., 82.6 feet * Unrecorded report ***** No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3 inch iron spring leaf with rocks packed around # 16 inch Maple stump w/lower blaze scar, N.95 W., 52.6 feet # Set new monument at corner position of spring leaf and established reference trees # Corner position as found is accepted as a careful and faithful perputation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Fil: Set Berntsen Monument No. 41NB30 adjacent to leaf spring, stamped to identify corner position * Established reference trees w/BT signs, blazed, scribed and painted * Set PK nails for measure w/Alum. I.D. Washers in the following reference trees - Haple 12, N.S6 W., 1.77 feet, '1/4BT' * Maple 1, N.E7 E., 32.03 feet, '1/4BT' * Maple 8, S.39 W.. 34.10 feet, '1/4BT' * Survey marker sign on 1 fibt steel post, S.13 W., 1.3 feet. * All bearing are magnetic.

Signed by Surveyor's Michigan License No. 75849

_ Date _ / Z / 10 / .

SURVEYOR 7 110. / 25549 / 5

RODERT L.
JAMROS
PROFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SUB-EYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN., 1983