Approved by Alger County Land Survey Remonumentation Pear Group Under Act 345 of P.A. of 1930 On 12-10199

Chainman

sed a Carles

SECTION

05-90

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Located In:	Corner Code #	F.,2D
Public Land Survey	48 16 T R T R	411 	TIME <u>\$30 Am</u> DEC 17 1997
 Property Controlling in Section Miscellaneous Property in Section 	T R T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY, MI Register of Deeds Stamp & File Number
5. Private Claims I. Dance do hereby certify that under require lines 1 and 2 above were in comanual of survey instructions Management or by a decree of a 5 above were in conformance videocree of a Court of Law; established as expressed below:	in a field survey on	n. of 1970, the comer points mentione ules therefore as required in the currer ent of the Interior, Bureau of Lan mer points mentioned in lines 3, 4 an ard of Professional Surveyors or by ted, re-monumented, recovered, found	2 -6 -5 -4 -3 -2 -1 -2 -3 -2 -1 -3 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1
A. Description of original n	nonument and accessories ar	nd/or subsequent restoration:	131

311: PLS - William Ives, OS, 1850 * Post set corner of Sections 27, 28, 33 % 34 * Sugar 1:, 3.70 E., 11 links * Beech B, N.58 W., 21 links ***** H.C. Lawrence, RLS, 1953 * Set scribed 6 inch post from original 8T, Beech B. M.SS W., 21 links * Witnesses - Sugar 8, M.73 1/4 E., 14.5 feet * Beech 9, S.12 E., 22.5 feet * Unrecorded ***** Robert L. Jamros, RLS. 1931 * Recovered post point of down wood post * Found Beech stump with scribing at a distance of 21 links from post point * Set 1/2 into ty 18 inch iron bar w/I.D. cap in place of gost point * Witnessas - Beech 13, 3.66 E., 14.68 feet * Maple 14, N.23 W., 32.48 feet : Maple 12, N.78 E., 22.56 feet * Maple 7, 8.54 E., 17.78 feet * Recorded in Liber 1, Page 406, Alger County corner records ***** No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2 inch iron bar w/I.D. cap * Recovered 2 exist. BT's of the 1953 unrecorded report and the 1981 record report, all others have been but down * Installed new monument, renewed exist. 8T's and established additional reference trees. * Corner position as found is accepted as a careful and faithful perpetuation of the position of the original corrner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

311: Set Bernsten Monument No. A1M830, stamped to identify corner position. Established reference trees w/BT signs, blazed, spribed and painted. Set PK nails for measure w/Alum. 1.3. washers in the following reference trees - Exist. Beech 16, 5.07 E., 14.66 feet, dbl. blzt. * Beech 7, 3.30 W., 18.25 feet, *333 ET* * Exist. Maple 22, N.24 W., 32.37 feet, czl. blzd. * Beech 3, N.64 E., 21.46 feet, *332 ET' = Survey marker sign on 6 foot steel post. E.34 E., 0.90 feet * 411 bearings are magnetic.

Signed by 25649 Surveyor's Michigan License No.

AN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

JAMROS

REVISED MAY 14, 1975