

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 .. NR. 17 W ..

Alger

COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 26-27-34-35
DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap
WITNESSES TO CORNER 9" Hard Maple S 84° W 38 links
"S 34 NBT"
14" Hard Maple S 45° E 57 links
"S 35 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from one beech B.T. bearing NE of corner. Stump in poor condition. Corner found by Forestry Division Survey crew.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/4/57
REGISTERED LAND SURVEYOR