

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48. NR. 17. W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 23 and 26

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (1/4s NBT) N 20° W 15 Links

9" Cedar (1/4s NBT) S 32° E 28 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from hole left by post which was removed by unknown party. Distance east to corner and swamp edge and west to stream check good.

Note: This post was located by survey crew several years ago.

Corner was placed and witnessed August 10, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/14/60
REGISTERED LAND SURVEYOR
Billy D. Buckler