

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48. NR. 17. W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 34 and 35

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 18" Y. Birch (1/4s NBT) N 30° W 21 Links

6" Ash (1/4s NBT) S 52° E 23 Links

14" Cedar (1/4s NBT) N 15° E 17 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-witnessed as set by R. J. Brotherton (existing NBT's 18" Y. Birch and 6" Ash.) Corner replace from (Cedar 7" bearing S 52° W 31 Links) an original B.T.

Corner was placed and witnessed June 11, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 9/14/60