

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD ✓

T. 48. NR. 17. W

A l g e r . . . . . COUNTY

DESCRIPTION OF CORNER 1/4 corner between Section 33 and 34 . . . . .

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap . . . . .

WITNESSES TO CORNER 8" Cedar . . . . . (1/4s NBT) . . . . . N 19° E . . . . . 14 1/2 Links

6" Balsam . . . . . (1/4s NBT) . . . . . S 53° E . . . . . 04 Links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from possible B. T. face and axe mark visible, (Cedar 14" S 75° E 17 Links) checks well with stream and swamp edges to south and north.

Corner was placed and witnessed August 18, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler . . . . . DATE 9/15/60 . . . . .  
REGISTERED LAND SURVEYOR  
Billy D. Buckler