## DEC 27 1999

CTION	
	CTION

Signed by

Surveyor's Michigan License No.

## LAND CORNER RECORDATION CERTIFICATE

$(\mathbf{r}_{i}, \mathbf{r}_{i})$	
Annroyed by Alger County	
Approved by Alger County Lend Survey Remonumentation	
Peer Group Under Act 345 of P.A. of 1990 On 12-81999	
P.A. of 1990 On 12-8 19 <b>9</b> 9	
TE Mulder Colson	
TE Guell Warren	<b></b>

P.A. of 1990 Or	12-	P1999	-
Hugh	Dove	als	2
	irman	······································	<u>,                                     </u>

	Filing Requirem	ent of Act 74, Mich. I	P.A. 1970	Ottommen
Alger (County)	Located In:	Corner Code #	ı	05-176
(oddiny)				1:46
1. Public Land Survey	T _48N_R_15W_	M1	~	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	T 48N R 4W	Al	TIME	1:30 p.m.
	T 49N R 14W	A13	_	
	T <u>44N</u> R <u>15 W</u>	MI3	į į	EC 1 5 1999
2. Property Controlling	S T R		NON	ALD W. KINNUNEN
in Section	S T R			GISTER OF DEEDS
3. Miscellaneous	S T R	<u> </u>		LGER COUNTY, MI
Property in Section	S T R		Hegister of Deed	ds Stamp & File Number
4. Lot No.	Recorded Plat			
			A B C	D E F G H I J K L I
			2 6	-Ś╌╂┈╡╌╂┈┇╼┼┈┆╌
	,		3	<del>                                     </del>
	•		4 7 1-	-6
i, Robert L. Jamros	, in a field survey onSepter	mber 17, 1999 , 19	, 5	<del>                                     </del>
do hereby state that under re	quirements of P.A. 74, Michigan P.A. o	of 1970, the corner points m	entioned 6 18	-1716151413
	conformance with regulations and rules			
•	ns of the United States Department of a Court of Law and/or that the corne			
	e with the rules of the Michigan Board			20 21 22 23 24
	ablished, re-established, monumented	•	d, found	
as expressed below:	•		10 30	29 28 27 26 25
NOTE: Not more than 2 co	orners, all in the same town and ra	nge, may be recorded	11	<del></del>
on this certificate.			12 31	32 33 34 35 36
Mi: PLS * John Burt, DS, Sugar 10°, N.63 E., 47 lin original BT, Beech stump. Unrecorded. ***** C.C.I. (6°, N.68 E., 7.7 feet. * U and 1960 unrecorded report 18°, N.72 E., 45.9 feet (5 Page 368, Alger County Con B. Description of corner Mi: Located corner search iron truck axle. Also for	I monument and accessories and 1841. * Set post corner of Townshinks. ****** C.C.I.Co., Land Corner * Original Haple BT remains noted Co., Land Corner Record. * T.J. Mc Unrecorded. ****** Robert E. Schmelts. * Set 1° iron pipe with brass 131 NBT). * S.Maple 10°, S.03 E., rner Records. ****** No other subsequence found and/or method and area by calculated position and 11 BT of the 1967 report and 3 BT's. Existing corner monument	nip 48 and 49 North, Ran Record. * Ray J. Brothe d. * 16 Sugar, S.05 W., Claren, 1967. * Found tr ling, RLS, 1980. * Found cap next to truck axle. 25.2 feet (S6 NBT). * Sequent restoration of re pplied in restoring or re- standard field survey m BT's of the 1980 report	ges 14 and 15 West. * Be rton, RLS, 1949. * Set a 25.5 links. * 3" Sugar, uck axle. * R.Maple 7", iron truck axle and acc * H.Maple 7", N.10 E., .Maple 9", S.42 W., 49.5 cord.  establishing corner: ethods. Found 1" iron p All other BT's destro	n iron truck axle from N.40 W., 30.5 links. * S.76 W., 7.0 feet. * R.Maple essories as noted in the 1949 8.0 feet (S36 NBT). * Beech' feet (S1 NBT). * Liber 1,  ipe with brass cap and an yed in logging operations.
•				
			•	
•				
C. Description of monum	nent for corner and accessories e	stablished to perpetuate	e locating the position of	the corner:
	with brass cap. * Renewed existi			
washers for measure in the	e following: Existing - Maple 10", 19 feet. * Existing - Maple 20", S	N.10 E., 7.98 feet, * 1	Existing - Maple 14", N.6 urvey marker sign on 6 fo	of E., 8.00 feet. * Existing pot steel post, S.27 E., 1.5  OF MICHIGAN  BERT L2
				MROS **

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

SURVEYOR No. 25849