DEC 27 1999 .

MEYEY &

For	corners	in

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Land Survey Rea	สอบของอย่อย่อย
Peer Group Un P.A. of 1990 On	der Act 345 of
P.A. of 1990 On _	12-819.99
$\mathcal{M}_{i+1}$	dulalson
_ Ann	a worker

Approved by Alans County

OLO I	Filing Requir	rement of Act 74, Mich. P.A	A. 1970 Chairnan
Alger (County)	Located In:	Comer Code #	05-177
Public Land Survey	T <u>48N</u> R <u>15N</u> T <u>48N</u> R <u>14</u> N T R	V AZ V	TIME 1:30 PA
Property Controlling in Section     Miscellaneous Property in Section	T R S T R S T R S T R		DEC 1.5 1999  DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No, 5. Private Claims,	Recorded Plat		A B C D E F G H J K L M
do hereby state that under r in lines 1 and 2 above were in manual of survey instruction Management or by a decree 5 above were in conformant	, in a field survey on Occupant of P.A. 74, Michigan Proconformance with regulations and one of the United States Departs of a Court of Law and/or that the coewith the rules of the Michigan Established, re-established, monume	A. of 1970, the corner points ment rules therefore as required in the coment of the Interior, Bureau of corner points mentioned in lines 3, 3 and of Land Surveyors or	ntioned current
NOTE: Not more than 2 con this certificate	corners, all in the same town an	d range, may be recorded	11

A. Description of original monument and accessories and/or subsequent restoration:

M2: PLS \* William A. Burt, DS, 1841. \* Set quarter section post. \* Beech 11", S.63 W., 36 links. \* Beech 10", N.41 E., 25 links. \*\*\*\*\*
C.C.I. Co., Land Corner Record. \* T.J. Mclaren, 1967. \* Set post on corrected line, 40.0 chains North of established section corner. \*
Sugar 9", S.67 W., 16.3 feet. \* Sugar 8", N.74 E., 19.8 feet. \* Unrecorded. \*\*\*\*\*\* Robert E. Schmeling, RLS, 1980. \* Found no evidence
of original bearing trees. \* Found stake point and 2 BT's of the 1967 unrecorded report. \* Set 1" iron pipe with brass cap at stake
point location with reference to existing BT's. \* H.Maple 8", N.14 W., 32.7 feet (1/4 S1 NBT). \* H.Maple 11", S.30 E., 27.3 feet (1/4
S6 NBT). \* Y.Birch 9", S.71 W., 25.4 feet (1/4 S1 NBT). \* Liber 1, Page 355, Alger County Corner Records. \*\*\*\*\*\* No other subsequent
restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M2: Located corner search area by calculated position and standard field survey methods. Found 1° iron pipe with brass cap and 3 references of the 1980 report. Also found 2 references of the 1967 unrecorded report. Existing monument and all references are in good condition. Existing corner monument as found lies 1.6 feet west of line and 10.8 feet south of proportional position between section corners 1/2 mile north and 1/2 mile south. Renewed existing references. Existing monument as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

25849

M2: Existing 1" iron pipe with brass cap. \* Renewed existing references with BT signs and paint. Set PK nails with aluminum I.D. washers for measure in the following: Existing - Y.Birch 12", S.74 W., 25.31 feet. \* Maple 18", N.11 W., 32.40 feet. \* Maple 16", S.29 E., 27.37 feet. \* Maple 16", N.73 E., 19.82 feet. \* Survey marker sign on 6 foot steel post, S.63 E., 1.5 feet. \* All bearings are magnetic.

Signed by filmet & pm

Surveyor's Michigan License No.

Date Dec

No. 25849

ROBERT L.
JAMROS
PROFESSIONAL
SURVEYOR