Approved by	Alger County
Approved by Land Survey Ro	moormentali on
- Poer Group Un	
P.A. of 1999 On.	3-24 10 97

P.A. of 1999 On 3-24 19.97

Suald Calson

For corners in

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

5-27

(County)	Located III.	Comer Code #		F	ILED			
Public Land Survey	T 49N R 13W	A3	TIN	ΛΕ <u></u>	2:00	<u>}</u>		
	T <u>49NR 14W</u> T <u>R</u> T R	M3	5.4		3 1 19	- •		
Property Controlling in Section			UC	NALD V REGISTEI WUGER (R OF DE	FAS	N	
3. Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number					
4. Lot No	_ , Recorded Plat		A I	3 C D	E F G	н (.1	K L M
	· · · · · · · · · · · · · · · · · · ·			ŢŢ	ÌÌĬ	Ï	Ţ	
in lines 1 and 2 above were manual of survey instruct Management or by a decre	, in a field survey on er requirements of P.A. 74, Michigan P.A. e in conformance with regulations and ru ctions of the United States Departme ee of a Court of Law and/or that the con	les therefore as required in the cu ent of the Interior, Bureau of I ner points mentioned in lines 3, 4	rrent \$ 7 Land \$ 7 and \$ 8 19	17-	16-21-	10-15-15-122-1	—11 —14— —23—	12-13-13-24-
	ance with the rules of the Michigan Boa established, re-established, monumente			- 29	28	-27	26	25
NOTE: Not more than 4 on this certificat	4 corners, all in the same town and i te.	range, may be recorded	12 -31 13	32	33	34	-35 -	36-
A3: PLS - John Burt, links * Beech 5, N.37 ***** James Roundtree and 26" long, * Refer	inal monument and accessories and DS, for William A. Burt, DS, 1841, 7 E., 26 links. * Geo. E. Adair, DS e, CS, 1908. * Iron Post driven accemces, 9" Cedar post, SE, 69 links. * References, P. Pole, S.32 E. 48	Set post corner of Sections , 1851. * Post, Y.Birch 15, Nording to field notes and bar . ***** M.S.H.D., Project No.	1 & 12, T.49N., 4.71 W., 33 links rren trees in cut . DS 610(3) 1958.	. * Beech in count * 1 1/2	n 12, S.A Ly road, ' iron pi	72 E., 1 1/4 ipe 1.3	24 li " in d 37 fee	nks. liam. t East

in L.1, P.113, Alger County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A3: Found 1 1/2' iron pipe in monument box 1 foot East of centerline of pavement on State Highway M-77, centerline of gravel road west, and 4 feet North of centerline gravel road East. Measurements to corners North and South as part of a Section Subdivision check well. References of 1958 and 1971 report not found. Established new references. Monument at existing corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

Davis, RLS, 1971. * Monument box in highway, apprarently set by the Michigan State Highway Dept. * Witness, Centerline of Elec. Pole, S.E., 44.20 feet. * Centerline of Guy pole, S.W., 48.30 feet. * Centerline of Highway M-77, West, 0.90 feet. * Recorded in L.1, P.1, Alger County Records. ***** Gerald W. Carlson, RLS, 1977.* Found 1 1/4' pipe in monument box in centerline of M-77 and centerline of E-W gravel road.* References, P.P., S.38 E., 48.17'.* S.P., N.30 E., 52.64'.* T.P., S.55 W., 44.23'.* T.P., S.33 W., 61.75'.* Recorded

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A3: Installed 5/8° X 18° Rebar w/ 3 1/4° Aluminum Cap inside of existing 1 1/2° pipe, stamped to identify corner position. Corner position lies within the improved area of the Village of Grand Marais and along the M-77 corridor. Used only PK nails for measure w/ Alum. I.D. washers in the following reference objects. * W. Birch 6', N.44 W., 68.45 feet. * Guy Pole, S.57 W., 44.22 feet. * Guy Pole, N.45 E., 58.33 feet. * Power Pole with overhead, S.34 E., 48.20 feet. * All bearings are magnetic.

Signed by Signed by Surveyor's Michigan License No. 25849

PROTECTION
SURVEYOR

A NO.

.Date_

25 March, 1997

ORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983