Approved by Alger County
Approved by Alger County Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On 3-24 1997
P.A. 01 1950 Cil 1- 22 194/
Gueld Colson

Chairman

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

5-29

POF C	ALGER (County)	Located In:	Corner Code #		FILED	
1. P	ublic Land Survey	T <u>49N</u> R <u>13W</u> T R T R	<u>85</u>		21:00 p.m. R 3 1 1997	
in 3. M	roperty Controlling a Section discellaneous Property in Section	T R ST R ST R ST R		REGIS	D W. KINNUI STER OF DEED FR COUNTY, M Is Stamp & Fil	DS II
5. P	rivate Claims	, Recorded Plat		A B C	D E F G	H J K L M
do he in line manu Mana 5 abo	reby certify that under as 1 and 2 above were all of survey instructing agement or by a decretion age were in conformar	, in a field survey on requirements of P.A. 74, Michigan P.J. in conformance with regulations and rions of the United States Department of a Court of Law and/or that the conce with the rules of the Michigan Bostablished, re-established, monument	A. of 1970, the corner points mention rules therefore as required in the cultion the interior, Bureau of L part points mentioned in lines 3, 4 pard of Professional Surveyors or in	oned 6 18 19 18 19 19 19 10 10 10 10 10 10 10 10 10 10 10 10 10	17 16 1 -20 21 2 -29 28 2	22 23 24 27 26 25 25
NOTI	E: Not more than 4 on this certificate	comers, all in the same town and e.	l range, may be recorded	12 31	32 33 3	4-35-36-
85:	PLS - Francis Colma	nal monument and accessories a an, DS, 1851, Set quarter Section nks ***** Mel Davis, RLS, 1971.	n post on West border of Hemlo	ck land, C N&S * Heml d road. Set corner on	a direct line	with and at a

proportionate distance between the section corners to the East and West. * Witness, Axel Bar, North, 41.75 feet. * Centerline Elec. Pole, N.54 E., 51.80 feet. * Well point at fence corner, S.22 W., 48.55 feet. * Recorded in L.1, P.5, Alger County records. ***** Gerald W. Carlson, RLS, 1978. * Found bent iron pipe, replaced w/ 5/8° X 18° Iron w/ RLS cap. Two feet South of centerline of East-West road and 80 feet East of centerline of drive on South side of road. * Witness, Power Pole, N.56 E., 51.92 feet. * Axle bar, 1.5 feet high, N.07 E., 41.70 feet. * Well point at fence corner, S.22 W., 48.55 feet. * 4° W. Birch, N.26 W., 85.79 feet. * Recorded in L.1, P.175, Alger County Records. *****

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B5: Found 5/8" iron w/ RLS cap. Verified corner position by measurements from the reference objects on corner reports of 1971 and 1978. Replaced existing cap with 3 1/4° Aluminum Cap stamped to identify corner position. Renewed existing references and added additional references. Monument at existing corner position is accepted as a careful and faithful reestablishment of the position of the original

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B5: Set 3 1/4" Aluminum Cap stamped to identify corner position. * Renewed existing reference objects w/ BT signs and paint. * Established additional reference trees w/ BT signs, blazed, scribed and painted. * Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. * Balsam 7", \$.29 E., 54.07 feet, "1/48 BY". * Balsam 10", \$.60 W., 82.68 feet, "1/48 BT". * Exist. BT, W. Birch 12°, N.31 W., 86.07 feet, Existing blazes. * Exist. BT, Axle Shaft, N.08 E., 41.62 feet. * All bearings are magnetic.

Signed by Surveyor's Michigan License No.

 $\Box T$

March, 1997 25

PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14, 1975 REVISED JAN., 1983

No. 25849 Date