Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-12-1995 M. DOWC. Par

RTIFICATE . P.A. 1970 JAN 2 3 1996

COMMISSION

	LAND CORNER RECORDATION CE	
Chairman	Filing Requirement of Act 74, Mich	
For corners in	gquoo o	

_	Alger	Located In:	Corner Code ##	4-320
1.	(County) Public Land Survey	T <u>49H</u> R <u>13H</u> T R T R T R	-C7	REC'D and FILED
	Property Controlling in Section	S T R S T R		DONALD WINNIEM County Clerk
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No , R	ecorded Plat		A B C D E F G H I J K L !
5.	Private Claims			A B C D E F G H I J K L I
do in l cur Ma	hereby certify that under req lines 1 and 2 above were in rrent manual of survey instru nagement or by a decree of a	uirements of P.A. 74, Michigan P.A. conformance with regulations a actions of the United States Depail Court of Law and/or that the corn	e 21, 1995 , 19	ned the and 7 and 5 8 19 20 21 22 23 24
Co			of Land Surveyors or by a Decree -monumented, recovered, found	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C7: PLS-Francis Coleman, DS, 1851, Set post corner of sections 17,18,19 & 20 - Cedar 20", N.70 W., 47 links, Cedar 14", S.27 E., 15 links. Walter W. Gleason, County Surveyor, 1914. Set iron corner at section line intersections. No references given. Survey book of records, page 180. Alger County Records. Alger County Road Commission Notes, George Depen, County Surveyor, 1916, iron corner shown. References: Hemlock 9", N.37 W., 50 feet, Cedar 12', S.30 E., 50.50 feet. CCI Forestry Division, Land and Timber Examination Report. T.J.McLaren, 1952, indicates a 5° cedar post at corner position. No references given. Gerald W. Carlson, RLS, 1978, Set 5/8° rebar at intersection of north and east roads and at recorded bearing and distance from cedar witness tree. References: Cedar 20°, S.35 E., 51.08', Spruce 15", S.13 E., 40.47', W. Birch S.36 E., 42.57', W. Birch 10", N.47 E., 39.62', Filing No. 175 Alger County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C7: Found 5/8" rebar with idenification cap Number 24589 at the centerline of roads to North and East. Verified witnesses of the 1978 report to be in agreement with corner position. A search was made for GLO bearing tree positions, evidence has been lost. Corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C7: Placed Berntsen Cap no. RBD5325 on existing 5/8" rebar, stamped to identify corner position. Renewed existing reference trees w/ BT signs and paint. Established additional reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Y.Birch 16", N.40 E., 68.82 feet, " face Blzd.", Ex. W.Birch 8", S.18 W., 25.27 feet, " face Blzd.", Maple 4", N.40 W., 32.46 feet, ", S18 BT ", Y.Birch 6", S.52 E., 54.11 feet, " S20 BT ", All bearings are magnetic.

SA

OF MIC

ROBERT L

Surveyor's Michigan/License No.

Signed by

JAMROS AND SURVEYOR NO. orDet¢

PPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

REVISED JAN., 1983