Approved by Algor County Land Survey Romonumeniction
Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On 4-8 1995
-A. DI 1990 OII 4-8 1975

7				_
	44	10	r 1	
_		ald le	Carlson	_
_		Chairm	nan	-

## LAND CORNER RECORDATION CERTIFICATE

4	2	7	-
	$\sim$	,	•

REVISEO JAN . 1983

Chairman	Filing Regu	irement of Act 74, Mich. P.A	1.1970 4-277
For corners in	i iiing rieqe	mement of Act 74, wholl I .A	/- 4//
Alger (County)	Located In:	Corner Code ##	FILED
Public Land Survey	T49N R 13W T R T R		APR 20 1995
in Section S	T R S T R S T R S T R	EMONUMENTATION	DONALD W. KINNUNEM REGISTER OF STEPS Register of Deeds Stamp & File Number
	S T R	COMMISSION	visitor of postar clamp a time realizer
do hereby certify that under require in lines 1 and 2 above were in corcurrent manual of survey instruction Management or by a decree of a Corabove were in conformance with the Court of Law; established, re-est expressed below:  NOTE: Not more than 4 corner on this certificate.	a field survey on	ictober 12, 1994 , 19 P.A. of 1970, the corner points mentions and rules therefore as required in partment of the Interior, Bureau of Lawrence points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of re-monumented, recovered, found and range, may be recorded	ned the and 7
PLS-Francis Coleman, DS, 1851, Robert L. Jamros, RLS, 1987, F	Set Post Corner of Sectio , N.Pine 5', S.16 E., 24 Found 6' x 6' Granite Mar , N.67 W., 15.9 ft., R.Pi	ns 1 and 2 - N.Pine 4", N.57 W., links, N.Pine 8", S.77 W., 17 li ker Scribed "U.S.L.H.E." on th	38 links, N.Pine 5", N.21 E., 22 links. nks. Subsequent resoration by author unknown. se top of granite marker. References: W.Pine 12", se 12", N.64 E., 13.2 ft., Recorded in corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K1: Found in place a 6"x 6" granite marker scribed "U.S.L.H.E." on top. From existing monument found original GLO BT's in SW and NW positions, dead and down. Scribing and notch still visible. Found all Bearing Trees from 1987 report in excellent condition. Accepted existing monument and renewed existing reference trees.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K1: Set 5/8 x 5 Rebar w/ 3 1/4 Alum. Cap stamped to identify corner position, drilled and grouted into the top of existing granite monument. Renewed existing reference trees w/ BI signs and paint. Set PK nails for measure w/ brass I.O. washers in the following references trees. Ex. W.Pine 12', N.63 W., 16.03 feet, "S35 BT', Ex. R.pine 14", S.75 W., 54.13 feet, "S2 BT', Ex. W.pine 14", S.18 1/2 E., 29.25 feet, "S1 BT", Ex. W.Pine 16", N.68 E., 13.13 feet, "S36 BT", Steel witness post with Survey marker sign, NE, 2.0 feet, All bearings are magnetic.

		/. /			
Signed by	Talut &	Camson	Date	12 April, 1995	
Signed bySigned bySigned by		25849		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1	1971
Surveyor's Michigan Election	/			FEVISES MAY 14. 1	1975