Approved by Alger Col Land Survey Remonume	ntation .		; ; ;
Peer Group Under Act 3 P.A. of 1990 On 48  Secular Chairman  For corners in	19 <u>95</u> Land Corn	NER RECORDATION CER irement of Act 74, Mich.	
Alger (County)  1. Public Land Survey	' —— ' · ——	Corner Code ##  K3  SURVEY &  ONUMENTATION	APR 20 1995
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R	MAY 1 0 1995 COMMISSION	REGISTER CT STEEL Register of Deeds Stamp & File Number
4. Lot No, I 5. Private Claims	Recorded Plat		A B C D E F G H I J K
do hereby certify that under re in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance with Court of Law; established, expressed below:	, in a field survey on	A. of 1970, the corner points men and rules therefore as required artment of the Interior, Bureau of her points mentioned in lines 3, d of Land Surveyors or by a Dec e-monumented, recovered, for	ntioned d in the of Land 4 and 5 ree of a und as 10 30 29 28 27 26

A. Description of original monument and accessories and/or subsequent restoration:

K3: PLS-Francis Coleman, D5, 1851, Set post corner of sections 1,2,11 and 12, - Cedar 8", N.21 E., 26 links, Cedar 10", N.22 W., 34 links. A.C.R.C., H.H.Anderson,CE, 1935, Road alignment of Grand Marais East. Corner position noted by scale 959 ft. N. of centerline of road. No references given. Robert L. Jamros, RLS, 1987, Established corner by proportinate measurement. References: W.Birch 12\*, North, 69.75 ft., W.Birch Twin, 10'-12", N.08 W., 69.30 ft., W.Birch 16", N.20 E., 59.95 ft. Recorded in corner record No. 3-359, Alger County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K3: Found corner position with 1° Iron Pipe and RLS cap in Tagalder marsh approx. 600 ft. N. of the Sucker River. Corner position as stated in corner record no. 3-359 was set by double proportionate measurement and Section corners one mile west, one mile north, one mile east, and 1/4 section corner one-half mile south. A search was made for original GLO evidence with no positive results. Bearing trees of the 1987 report found in excellent condition. No other bearing objects are available. Corner lies on the southern edge of a small knoll in the open Tagalder marsh. Existing corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:
3: Set 2 1/4 x 30 Alum. Monument w/ 3 1/4 Alum. Cap over top of existing 1 Iron pipe. Stamped cap to identify corner position. Renewed existing reference trees w/ BT signs and paint. Set PK nails for measure w/ brass I.D. washers in the following reference trees. Ex. W.Birch 10", N.06 1/2 W., 69.21 feet, "S2 BT", Ex. W.Birch 12", N.02 E., 69.74 feet, "S2 BT", Ex. W.Birch 18', N.20 E., 59.96 feet, 'S1 BT', Steel witness post with Survey marker sign, S.46 N., 1.0 feet, All bearings are magnetic.

	D	7		
Signed by	fount of	lomos	Date	12 April, 1995
Surveyor's Michigan Licens	se No.	25849		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
/				REVISED MAY 14, 1975 REVISED JAN., 1983