SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Personumentation

on this certificate.

SOOT A E IIII.

P.A. of 1990 On <u>5/8</u> 19.76		o / 1938			
Grand Walson	LAND CORNE	MISSION R RECORDA	TION CERTIFICA	TE	
Con a consens in	Filing Require	ement of Act 7	74, Mich. P.A. 197	⁷⁰ 4-369	
For corners in	cated In:	Corner C	Code #	7-06/	
Alger (County)		3311131 6		FILED	
1. Public Land Survey	T 49N R13N T	М3		TIME 3:00 p.m.	
	T R T R			JUN 27 1996	
	_T R _T R		· · · · · ·	DONALD W. KINNUNEN	
3. Miscellaneous S	T R T R			REGISTER OF DEEDS ALGER COUNTY Register of Deeds Starrip & File Number	
4. Lot No, Recorded P	lat			A D O D E E O II I I I I	_
5. Private Claims				A B C D E F G H I J K	ት
				2 - 6 5 3 2 2	-
				3	t
				4 7 8 9 10 11	12·
I, Robert L. Jamros , in a field survey on March 05, 1996 , 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned				5	+
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current				6 18 17 16 15 14	13.
manual of survey instructions of the United States Department of the Interior, Bureau of Land				7	+
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and				8 19 20 21 22 23	24.
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found				9	+
as expressed below:	ълавнонец, тилитет	cu, re-monument	eu, recoverea, rouna	10 30 29 28 27 26 26	 25:

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

M3: PLS-John Burt, DS, 1841, Set post corner of sections 1 & 12 - 8.Ash (no size given), S.65 E., 32 links, 8.Ash 12°, N.57 W., 18 links, B.Ash 12, N.54 E., 45 links, B.Ash 12, S.57 W., 9 links.***** CCI Forestry Division, Land and Timber Examination Report, T.J.McLaren, 1950, Indicates a two inch iron pipe at corner position. No references were given.***** Michigan Department of Conservation, Forestry Division, Billy D. Buckler, RLS, 1953, Corner pointed out to me by B. McTiver, district forester in Newberry. Three original BT's still in place, poor condition. Set 1 pipe w/ 4 brass cap and established the following references, Balsam 10 , S.32 W., 22 links, Balsam 8°, N.68 E., 22 links. Recorded in Liber one on page 109A, Luce County Records. No other subsequent restoration.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

M3: Found 1" G.I.P. with 4" Brass cap driven in center hole of a 2' iron pipe high above the ground and unstable. Drove monument and pipe down to stable condition. Found BT's of the report of 1953 dead and down. Also found three other unrecorded BT's from a more recent survey in good condition, blazed and scribed. Established an additional BT and upgraded existing BT's to current Alger County standards. Monument position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M3: Stamped P.A. 345 in existing four inch brass capped Department of Conservation Monument. Renewed existing reference trees w/ BT signs and paint. Established additional reference trees w/BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Balsam 16", S.82 W., 14.67 feet, "12 BT", Ex. Maple 10", N.42 W., 17.43 feet, "1 BT", Ex. Balsam 14", N.50 E., 21.46 feet, "6 BT", Maple 14", S.45 E., 45.58 feet, "57 BT". Survey marker sign on six foot steel post, S.23 W., O.80 feet. All bearings are magnetic.

OF MICH

OFESSIO

JAMROS **PROFESSIONA** UNDERVEYOR'S **Date** No. Surveyor's Michigar License No. STATE BOARD OF RVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983