## SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Paer Group Under Act 845 of P.A. of 1990 On 5/8/1996

Chairman

JUL 3 0 1996

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

4-370

For corners in	Located In:	Corner Code #	i .
(County)			FILED
1. Public Land Survey	T 49N - P13W T R		TIME 3:00 p.m.
	T R T R		JUN 27 1996
Property Controlling in Section	S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS
Miscellaneous     Property in Section	ST R ST R		ALGER COUNTY. MI Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H ! J K L !  2 6 5 4 3 2 1 1 3
do hereby certify that under in lines 1 and 2 above were in manual of survey instruction. Management or by a decree 5 above were in conformant	requirements of P.A. 74, Michigan n conformance with regulations and ons of the United States Depair of a Court of Law and/or that the ce with the rules of the Michigan	P.A. of 1970, the corner points med d rules therefore as required in the trment of the Interior, Bureau o comer points mentioned in lines 3 Board of Professional Surveyors	ontioned 6 18 17 16 15 14 13 13 15 15 14 13 15 15 14 13 15 15 15 15 15 15 15 15 15 15 15 15 15
as expressed below:		ented, re-monumented, recovered	10 30 29 28 27 26 25 -
NOTE: Not more than 4 on this certificate	comers, all in the same town a	nd range, may be recorded	12 31 32 33 34 35 36
		and/or subsequent restoration	on:

M4: PLS-John Burt, D5, 1841, Set qr. section post - Sugar 6", S.08 E., 24 links, Sugar 6", N.58 W., 10 links.\*\*\*\*\* CCI Forestry Division, Land and Timber Examination Report, T.J. McLaren, 1950, Documented six inch post at corner position. No references were given.\*\*\*\* Michigan Department of Natural Resources, Billy D. Buckler, RLS, 1977, Corner re-established midway and on line between two section corners. No evidence of original corner. Set 1" pipe w/ 4" Aluminum cap and established the following references, Maple 20", N.62 W., 17.6 feet, Beech 12", S.47 E., 29.1 feet. Recorded in Liber one on page 238, Luce County Records. No other subsequent restoration.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M4: Found 1° G.I.P. with 4° Aluminum cap an a 6° flat faced wood post three feet high. Also found two BT's from the report of 1977 in good condition. Corner position checks well with other corners of section 12 documented by a section subdivision survey performed in 1985 by Robert L. Jamros, PS, Established additional BT's and upgraded existing BT's to current Alger County standards. Monument position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

N4: Stamped P.A. 345 in existing four inch aluminum capped monument. Renewed existing reference trees w/ BT signs and paint. Established additional reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Maple 24", N.61 W., 18.33 feet, "Blzd", Ex. Beech 16", S.44 E., 29.46 feet "BH Blz. NBT", Maple 8", N.14 E., 59.52 feet "1/4s BT", Beech 12', S.37 W., 49.29 feet, "1/4s BT". Survey marker sign on six foot steel post, S.63 W., 1.0 feet. All bearings are magnetic.

Signed by John A. Augus Surveyor's Michigan License No. 258

\_ Date \_

ROBERT L JAMPOS PROFESSION

> ONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983