SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On <u>5/8</u>19<u>96</u>

JUL 3 0 1998

<u>Herslel</u> W Chairman		ER RECORDATION CERTIFIC rement of Act 74, Mich. P.A. 1	
For corners in Alger (County)	Located In:	Corner Code #	FILED TIME 3:00p.m
1. Public Land Survey	T 49N Rt3W T R T R T R		JUN 27 1996 DONALD W. KINNUNEN
 Property Controlling in Section Miscellaneous Property in Section 			REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No 5. Private Claims	, Recorded Plat		A B C D E F G H I J K L I
do hereby certify that under in lines 1 and 2 above were manual of survey instruct Management or by a decre 5 above were in conformat	r requirements of P.A. 74, Michigan P., in conformance with regulations and it tions of the United States Departm se of a Court of Law and/or that the co nce with the rules of the Michigan Be	A. of 1970, the comer points mentione rules therefore as required in the currement of the Interior, Bureau of Lar orner points mentioned in lines 3, 4 are loard of Professional Surveyors or by inted, re-monumented, recovered, four	ed 6 18 17 16 15 14 13 14 13 15 16 16 15 14 13 15 16 16 16 16 16 16 16 16 16 16 16 16 16
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

M6: PLS-John Burt, DS, 1841, Set qr. section post - Birch 14", S.50 E., 33 links, Hemlock 7", N.47 W., 29 links.***** CCI Forestry Division, Land and Timber Examination Report, David C. West, 1968, Documented a four inch LES post at corner position. No references given.***** Michigan Department of Conservation, Forestry Division, Billy D. Buckler, RLS, 1972, Found a Painted Cedar post set by the Land Economic Survey (LES) during the 1930's. Found blazes on live timber to North, South and East. Corner lies 20 feet East of a woods road. Placed 1" pipe with 4" Aluminum cap at corner and established the following reference trees. 8" Hard Maple, S.17 W., 9.3 ft., 24" W.Pine, N.71 E., 58.0 ft., Recorded in Liber one on page 112, Luce County Records. No other subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M6: Corner location found by measuring from corner to North one half mile South along existing woods road which parallels section line. At corner position found 1° G.I.P. with 4° Aluminum cap in good condition. Also found BT in Northeast location in good condition, BT in Southwest location has been destroyed. Logging operations of the past years destroyed original BT locations. Established additional reference trees and upgraded existing BT to current Alger County standards. Monument position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M6: Stamped P.A. 345 in existing four inch brass capped Department of Conservation Monument. Renewed existing reference tree w/ BT signs and paint. Established additional reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. W.Pine 40", N.75 E., 58.96 feet, "Large Blaze", Beech 16", S.68 E., 61.83 feet, "1/4s BT", Maple 6", S.05 W., 18.11 feet, "1/4s BT", Maple 7", N.24 W., 50.45 feet, "1/4s BT". Survey marker sign on six foot steel post, S.46 E., 1.0 feet. All bearings are magnetic.

Signed by Jalut A. January
Surveyor's Michigen License No. Z5849

Date 12

FORM APPROVED BY MICHIGAN STATE BOARD OF PRO

ROBERT L.

JAMROS

PROFESSIONAL

SURVEYOR

No. , _ |

42584

L SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983