

✓

**MICHIGAN**  
**DEPARTMENT OF CONSERVATION**  
**FORESTRY DIVISION**

**LAND CORNER RECORD**

T. 42 .. NR. 13W ..

----- Alger -----

COUNTY

DESCRIPTION OF CORNER ----- Sec. Cor. 15-16-21-22 -----

DESCRIPTION OF CORNER MONUMENT ----- 1" Pipe with 4" Brass Cap -----

WITNESSES TO CORNER ----- 13" H. Maple (S15 NBT) N20°E 49½ lks. -----

----- 11" S. Maple (S16 NBT) N26°W 80½ lks. -----

----- 8" S. Maple (S22 NBT) S9°W 61 lks. -----

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

Replaced cor. from Sugar B.T. S17°E 18 lks. Tree green has been chopped out and scribe marks obliterated. Found two 1" Iron Pipes at cor. cor. lies 30 lks. east of approx. road intersection and in line with road to west. Cor. found by Forestry Division Survey Crew. Cor. placed and wit. 6/26/58 with Frank Bray.

**SURVEYORS SEAL**

*Billy D. Buckler*  
SIGNED ----- Billy D. Buckler -----  
REGISTERED LAND SURVEYOR

DATE -- 7/30/59