

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49. NR. 13. W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 13 and 14

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4 " Brass Cap

WITNESSES TO CORNER 8" Soft Maple (1/4s NBT) S 80° W 32 Links

6" Soft Maple (1/4s NBT) S 19° E 24 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between Section Corners.

Corner was placed and witnessed June 30, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/21/60
REGISTERED LAND SURVEYOR
Billy D. Buckler