

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR 12-13 W.

A l g e r & L u c e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 24, 25, 19, 30 . . .

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Soft Maple . . (S 30 NBT) . . S 02° E . . 51 Links . .

5" Soft Maple . . (S 24 NBT) . . N 74° W . . 16 Links . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from evidence of Blazes on old down Hemlock which
may have been the corner tree in original notes. Measurements to corners in vicinity
check well.

Corner was placed and witnessed June 28, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/21/60 -
REGISTERED LAND SURVEYOR
Billy D. Buckler