

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49. NR. 13. W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 22 and 23

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 36" W. Pine Stump (NBT) S 25° E 134 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by placing it midway and on line between section corners.

Corner was placed and witnessed June 27, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/21/60
REGISTERED LAND SURVEYOR
Billy D. Buckler