MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_49. NR 15 -W.

			A 1ger COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 15 & 16
DESCRIPTION	OF	CORNER	MONUMENT_3/4" Iron Pipe
WIT TNESSES	то	CORNER	12" S. Maple - S 60 E - 41 Links
			10* 8. Maple - 8 33 W - 28 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by E. C. Hall, District Forester, of Shingleton. One original B.T. in place, in poor condition. Corner had been previously leasted and perpetuated by unknown Surveyor. Pipe is buried 2" below surface, in trail road.

Corner was witnessed July 19, 1951.

SURVEYOR'S SEAL

SIGNED Seam C. Sida males DATE 7/26/51