

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.49 .. NR.15.W ..

Alger COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 19, 20, 29, 30 ..

DESCRIPTION OF CORNER MONUMENT 1" pipe with 1/2" brass cap ..

WITNESSES TO CORNER 6" Red Pine N 32° E 92 links ..

8" Red Oak S 38° E 17 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one W. Pine B.T. in poor condition. Notch remaining on stump.

Corner found by Forestry Division Survey crew while making a partial re-survey of this area.

Corner placed and witnessed August 24, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 9/4/56
REGISTERED LAND SURVEYOR