

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 15 W.

Alger COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sec.'s 29-30

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 32" W. Pine Stump N 67° W 16 1/2 links  
Marked "1/4 S NBT"

40" W. Pine Stump N 33° E 68 links  
Marked "1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one white pine B.T. bearing S 44° W 21 links in poor condition.

Distance checks north and south to good corners.

1/4 Corner found by Forestry Division Survey Crew while making a resurvey of this township.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 5/24/57  
REGISTERED LAND SURVEYOR