MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_49_ NR_15 W__

					Alger	COUNTY	
DESCRIPTION	OF	CORNER	Section corn	er common	to Sec. 18 29-30	<u>)-31-32</u>	
DESCRIPTION	OF	OF CORNER MONUMENT 1" pipe with 4" brass cap					
WITTNESSES	то	CORNER	24" W. Pine		S 54 E		
			24" W. Pine	stub	N 58° E	118 links	
					"S 29 NBT"		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one yellow pine B.T. down and in poor condition.

Corner found by Forestry Division Survey Crew.

Placed location poster on red pine 17.00 chs. east of corner.

SURVEYORS SEAL

SIGNED_Billy D. Suchla DATE 11/5/57_