MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 15 W

			-	Alger	COUN	ΤY
DESCRIPTION	OF	CORNER	Section corner	common to Sec. s	20-21-28-29	
DESCRIPTION	OF	CORNER	MONUMENT1	pipe_with_4" bra	mes_cap	
WITTNESSES	то	CORNER	14" Red Pine	N 22 ⁰ E "15 21 NBT" -	36½ links	
			10" Red Pine	N 15 ⁰ W	62 links	
			13" Hemlock	"S 20 NBT" S 2° W	47½ links	
				"S 29 NBT"		
					. 	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from two hemlock B.T.s bearing N 49° W 14 links and S 36° E 31 links. Both stumps down and shattered but scribe marks very plain on wood fragments.

Corner found while checking lines run by Survey Crew.

SURVEYORS SEAL

SIGNED Silly Suckles DATE 11/6/57 REGISTERED LAND SURVEYOR