

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49 NR. 15 W

Alger COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 22, 23, 26, 27

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" W. Pine (twin) (S 23 NBT) N 81° E 70 Links

12" W. Pine (S 27 NBT) S 35° W 38 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from one W. Pine Stump bottom N 44 1/2 E

45 Links. The other Pine B.T. could have been removed in Road Construction.

Position fits for proportionate measure East and West. Corner lies in logging road.

Corner was placed and witnessed June 17, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/27/60
REGISTERED LAND SURVEYOR
Billy D. Buckler