

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 42. NR. 15. W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 28 and 33

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 14" Red Pine (1/4s NBT) S 25° E 28 Links

13" Red Pine (1/4s NBT) N 52° E 77 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of spruce B.T.'s. Placed location poster 2 1/2 chains north on road.

Corner was placed and witnessed June 17, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/27/60
REGISTERED LAND SURVEYOR
Billy D. Buckler