

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49. NR. 15. W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 22 and 23

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 18" W. Pine Stump (1/4" NBT) N 27° W 123 Links

36" W. Pine Stump (1/4" NBT) N 70° E 88 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of original corner.

Squared and scribed 8" Aspen at corner.

Corner was placed and witnessed June 17, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 7/27/60