

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 49. NR. 15. W

Alger COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 21 and 28

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Red Pine (1/4" NBT) N 68° W 15 Links

12" Red Pine (1/4" NBT) S 25° E 35 Links

8" W. Pine (1/4" NBT) N 2° E 12 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one Hemlock S.T. down and in very poor condition, bearing S 25° W, 15 Links. No evidence of use at corner.

This corner was placed and witnessed June 20, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/27/60
REGISTERED LAND SURVEYOR
Billy D. Buckler