

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 15. W

A l g e r COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 9 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Cedar (1/4" NBT) N 42° E 19 1/2 Links

7" Hard Maple (1/4" NBT) S 37° E 22 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from one Hemlock B.T. bearing S 29° E 12 Links

A stub in excellent condition. Found by E. C. Hall, D. F.

Corner was placed and witnessed August 17, 1960 with Hall, D. F.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/14/60