

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 15. W

Alger COUNTY

DESCRIPTION OF CORNER Witness corner to Meander corner between Sections
18 and 19 on Lake Superior.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" White Pine (BT) S 6° E 24 Links

7" Red Pine (BT) N 82° E 24 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Witness corner lies on top of high bank. Witness corner lies 3.06 chains east of Meander corner. Placed Witness Corner to Meander Corner 3.06 chains East of position of Meander, which was removed by ice action.

Corner was placed and witnessed 7/8/59.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/29/60
REGISTERED LAND SURVEYOR
Billy D. Buckler