SURVEY & REMONUMENTATION

Land Sun of the Linear rush Feer Group Uniter Moteville 5 of PA of 1990 Cm. 12-10/1997

FEB 1 9 1998

05-89

Gueld Werlson	-	SECTION	NC
Chairman	EAMD COMMEN	RECORDATION CERTIFICATION OF THE PROPERTY OF T	
For corners in	Filing Requirem	cent of Act 74, Mich. P.A. Corner Code #	. 1970 F.L.ID
Caunty)	Located in.	Collier Code #	TIME Siso A.M.
Public Land Survey	49 13 T <u></u> R T <u>49N</u> R <u>14W</u> T R	AG MG	DEC 17 1997 DONALD W. KINNUNEN
 Property Controlling in Section Miscellaneous Property in Section 	T R S T R S T R S T R S T R		REGISTER OF DEEDS GER COUNTY. MI Register of Deeds Stamp & File Number
4. Lot No, Re 5. Private Claims	ecorded Plat		A B C D E F G H J K L ?
a. Scremi L. Lavres	in a field survey on	er [7 1997 19	3 4 7 8 9 10 11 12 5
do hereby certify that under require lines 1 and 2 above were in commanual of survey instructions. Management or by a decree of 5 above were in conformance of the conformance of a Court of Law; establias expressed below:	uirements of P.A. 74, Michigan P.A. on formance with regulations and rule of the United States Department a Court of Law and/or that the community the rules of the Michigan Boar bilished, re-established, monumented	of 1970, the corner points mentic is therefore as required in the cur it of the interior, Bureau of L er points mentioned in lines 3, 4 d of Professional Surveyors of I d, re-monumented, recovered, for	oned rent 7 16 15 14 13 13 13 14 13 14 13 14 15 14 15 14 15 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 con on this certificate.	ners, all in the same town and ra	ange, may be recorded	12 31 32 33 34 35 35 35 35
A. Description of original r	nonument and accessories and	Vor subsequent restoration:	
Depew, County Eurveyor, 191 Construction Plans for M-77 Inch from pipe at East edge	17 # Set iron corner on true lis 7, 1958 # Corner position not si e of pavement of M-77, old brow	ne at equal distance * No re nown, only wire fence to Eas en fence to East and West *	# Beech 13, H.25 W., 22 links ***** George L. Ferences given ***** M.O.S.H., Survey and ##### Seraid #. Carlson, RL5, 1978 * Found 1/2 Witnesses - Maple 5, 5.43 W., 22.71 feet * Triple

Maple 5. 8.38 J., 64.40 feet r Power Pole, N.13 E., 92.20 feet r Recorded it Eiber 1, Page 175. Alger County Corner Records ***** Weil E. Hill RLS, 1989 * Found 1/2 inch iron pipe on East abge of pavement and accepted, placed monument box * Witnesses - 5.53 W., 75.70 feet, b Maple : 5.70 M., 61.76 feet, 11 Maple : West, b5.43 feet, 12 Maple : M.10 E., 92.27 feet, Power Pole : Recorded in Liber 4, Page 50, Alger County Corner Records ***** No other subsequent restoration recorded.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

A6: Found 1/2 inch Rebar w/I.D. cap no. 27447 (Neil E. Hill) in monument box, 11.6 feet East of centerline pavement on H-77 * Renewed exist. ET's and established additional references. * Measurements to corners North and South check well. Corner position is accepted and used locally. Accepted monument at this position as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A6: Replaced 1/2 lach Rebar with a 5/8 inch by 18 inch Repar W/Berntsen Alum, cap no. RBD 5325, stamped to identify corner position * Renewed exist. IT's w/BT signs and established additional references w/BT signs * Set PK nails w/Alus. I.D. washers for measure in the following * Exist. ST. Power Pole, N.14 E., 92.36 feet, sprited "BT" at base, no signs * Red Pine 16. 1.42 E., 55.65 feet * Maple 14, N.83 W., obla9 feet * Exist. 3T, Maple 7, S.44 W., 82.57 feet * All bearings are magnetic.

Signed by 25849 Surveyor's Mich/gan License No

SURVEYORS REVISED MAY 14, 1975