APR 0 7 1998 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

			, % 88	
For Corners in SECTIONLocated In:	Corner Code #	1	E-202	771
ALLEGAN (county)		Ì	JAN :	η =
		j i	Z1	
1. Public Land Survey T 1N R 11W CORNER COMMON TO T R	√M-7	į	関の影響	[1]
CORNER COMMON TO T R SECTIONS 13 & 24 T R		į		$\mathcal{O}_{\mathbb{R}^n}$
GUN PLAIN TOWNSHIP TR			23	
ON RANGE LINE 2. Property Controlling S. T. D.		i	ν. ω	
2. Property Controlling S T R in Section S T R		 Register	of Deeds Stamp & I	File Number
3. Miscellaneous S T R Property in Sec. S T R				
4. Lot No, Recorded Plat				
5. Private Claims		A B C D E	<u> </u>	K_L M
1, Brian Reynolds, in a field survey on 10 JULY, 1997 do hereby cer	tify that under requirements	2 <u> 6 5 </u> 3 1 1	1 4 3 2	11
of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in line	s 1 and 2 above were in	4 . 7 . 8 .		1 12
conformance with regulations and rules therefore as required in the cr	urrent manual of survey	5 1		<u> </u>
instructions of the United States Department of the Interior, Bureau of a decree of a Court of Law and/or that the corner points mentioned in	Land Management or by	6 18 17	16 15 14	13
were in conformance with the rules of the Michigan Board of Land Sur	rvevors or by a Decree	7	21 22 23	1 24
of a Court of Law; established, re-established, monumented, re-monu	mented, recovered, found	9		
as expressed below.		10 30 29		25
NOTE: Not more than 2 corners, all in the same town and range,	may be recorded	11 <u> </u>		1 36 1
on this certificate.	_	13 1 1 1 1	95 94 95	
A. Description of original monument and accessories and/o	or subsequent restoratio	n:		
1. GENERAL LAND OFFICE: JOHN MULLETT, D.S., 1825 (R11W W. OAK 9 N25 1/2W 133 Do. 1/4	, P.10) "80.00 SET POST (6 S26W 57	CORNER TO SECTIONS 1	3 & 24"	
2. GENERAL LAND OFFICE: SYLVESTER SIBLEY, D.S., 1826 (R10W, P.33 FOR A-7, T1N, R10W BARRY COUNTY RECORDS) "WEST 82.47 INTERSECTED				
W. BOUNDARY 78 N. OF POST" A. W. OAK 18 S35E 80 A. B. OAK 28 N62E 113				
3. NO MENTION OF THIS CORNER COULD BE FOUND IN THE BARRY OR ALLEGAN COUNTY SURVEYOR RECORDS. 4. ALLEGAN COUNTY ROAD COMMISSION WITNESS CARD: c. 1923 "LARGE STONE" OAK SE 36.4 OAK NW 94.9 ELM SW 79.1				
N25E S.W. COR. STORE 71.0 S43W N.E. COR, STORE 63.8' S55W 12" CHERRY 38.6				
5. ALLEGAN COUNTY ROAD COMM. WITNESS CARD:C.1929 "LARGE STONE" 12" HICKORY NW 72.9 24" HICKORY SE 52.5 NE COR STORE S.W. 63.6 6. LAND CORNER RECORDATION CERTIFICATE: #44 (BARRY COUNTY RECORDS) DONALD R. GILCHRIST, P.S. #13583, 11-13-72,				
WITNESSES FOR A-7, T1N, R10W, "42" NORTH OF GUN PLAIN TWP. CORNER"				
7. ROAD COMM. WITNESS CARD: FROM DAVID F. PEABODY, P.S. #25866, OCT., 1980 "FOUND NAIL OVER IRON"				
24" HICKORY N70"E 52" P. POLE N50"W 72.4" NE (8. LAND CORNER RECORDATION CERTIFICATE: LIBER 3, PAG	COR. STORE \$45°W 57	V D C #05000 7 87 W4		
"FOUND NAIL OVER IRON" 24" HICKORY N70°E 52" P. POLE N50"W 72.4" NE COR. STORE 545"W 57				
9. ALLEGAN COUNTY ROAD COMM. WITNESS CARD: NO NAM	E OR DATE, 1/2" PIPE 42	.24° SOUTH OF A-7, T1N, I	₹10W	
B. Description of corner evidence found and/or method app	lied in restoring or reest	ahlishing corner		
FOUND 60d NAIL INSIDE A 1/2" PIPE, SET IN CONCRETE INSIDE A MONUMENT BOX. FOUND OAK SE WITNESS FROM ITEM #4, 24"				
HICKORY SE WITNESS FROM #5, AND ALL WITNESSES FROM #6, #7, #8, & #9. ACCEPTED FOUND 60d NAIL IN 1/2" PIPE, IN CONCRETE INSIDE A MONUMENT BOX AS BEST EVIDENCE OF CORNER POSITION.				
LEFT 60d NAIL INSIDE A 1/2" PIPE, SET IN CONCRETE	I E INSIDE A MONUME INSIDE A MONUMENT	NT BOX AS BEST EVII BOX IN PLACE	DENCE OF CORNER	POSITION.
Peer group approved Aug. 12, 1997.		DOX III I DAOL.		
Peer group approved Aug. 12, 1997. C. Description of monument for corner and accessories esta	ablished to perpetuate lo	cating the position of the	ie corner:	
60d NAIL INSIDE A 1/2" PIPE, SET IN CONCRETE INSIDE A MONUMENT BOX. SET 20d NAIL W/METAL REMON TAG IN THE SOUTH SIDE OF A UTILITY POLE N59°W 72.77'				
SET 20d NAIL W/METAL REMON TAG IN THE WE	ST SIDE OF A UTILI	TY POLE N25°W 70.	23'	
FOUND "PK" IN THE WEST SIDE OF A UTILITY PO FOUND "PK" IN THE EAST SIDE OF A UTILITY PO	DLE N11°E 111.26'		11.00	N.C. W.
NORTHEAST CORNER STORE \$53°W 57.44'	LE 341 E 34.30			IAN
A-7, T1N, R10W LIES N00°00'56"W 42.23'			REYN	IOLDS
40"+/- SOUTH OF CENTERLINE ROAD EAST 8*+/- SOUTH OF CENTERLINE ROAD WEST	ADDROVED DELCAN	IN SERVICE A TRANSPORT OF COLUMN		EYOR
1'+/- EAST OF NORTH-SOUTH CENTERLINE	P.A. 34	UMENTATION CORNER IS OF 1990	T / \	0.
	ALLEGA DATE APPROVED			
	COUNTY REP.	K.V.O.	(4)	0 1 2
				-
		8-13-9	-	
Signed by Surveyor's Michigan License No31602	Date	·	· · · · · · · · · · · · · · · · · · ·	
Surveyor's Michigan License No 31602	FOF	RM APPROVED BY MICHIGAN STA VISED MAY 14, 1975 REVISED .	JE BOARD OF LAND SURVEY JANUARY, 1983 REVISED (ORS. JAN. 28, 1971 OCTOBER 1996
00 01 ՁՈՒՈ ₅₅₅₉				