

ALLEGAN COUNTY REMONUMENTATION

APR 0.7 1988 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		, % 98
For Corners in SECTION Located In:	Corner Code #	ا کیمید کے ا
ALLEGAN		ES C N
(county)	•	121 PH
1. Public Land Survey T 1N R 11W		
CORNER COMMON TO T R SECTIONS 24 & 25 T R		
GUN PLAIN TOWNSHIP TR		: 2
ON RANGE LINE		ري چي اور
	_	i
2. Property Controlling STR in Section STR	- -	Register of Deeds Stamp & File Number
3. Miscellaneous S TR Property in Sec. S TR		
Property in Sec. S RR		
d 1 -1 his Described Diek		
4. Lot No, Recorded Plat		ABCDEFGHIJKLM
5. Private Claims		2 6 5 4 3 2 1
I, Brian Reynolds, in a field survey on 10 JULY, 1997 do here	eby certify that under requirements	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
of P.A. 74, Michigan P.A. of 1970, the corner points mentioned		4 7 1 8 1 9 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey 6		
instructions of the United States Department of the Interior, Bureau of Land Management or by		
a decree of a Court of Law and/or that the corner points mention	ned in lines 3, 4, and 5 above	7 [
were in conformance with the rules of the Michigan Board of La		8 19 20 21 22 23 24
of a Court of Law; established, re-established, monumented, re-	-monumented, recovered, found	9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
as expressed below.		10 30 29 28 27 26 25
NOTE: Not were then 2 and a still the same town and	sance may be recorded	11
NOTE: Not more than 2 corners, all in the same town and range, may be recorded 12 31 32 33 34 35 36 on this certificate,		
A. Description of original monument and accessories and/or subsequent restoration:		
1. GENERAL LAND OFFICE: JOHN MULLETT, D.S., 1825 (R11W, P.10) "80.00 SET POST CORNER TO SECTIONS 24 & 25"		
TAMARACK 6 N18 1/2W 26	Do. 6 S23 1/2W 27	
2. GENERAL LAND OFFICE: SYLVESTER SIBLEY	/, D.S., 1826 (R10W, P.32 FOR A	A-9, T1N, R10W, BARRY COUNTY RECORDS)
"WEST 82.39 INTERSECTED W. BOUNDA	ARY 46 N. OF POST" A TA	MARACK 7 N21W 33 A. B. ASH 8 S35E 44
3. NO MENTION OF THIS CORNER COULD BE FO	OUND IN THE BARRY OR ALLE	GAN COUNTY SURVEYOR RECORDS.
4. RECORDED PLAT OF "SHANGRI-LA NUMBER TWO" AS RECORDED IN (BARRY COUNTY RECORDS) LIBER 5 OF PLATS,		
ON PAGES 71-73, SEPTEMBER 26, 1969, CORNER WAS NOT WITNESSED, BUT REFERENCED		
AS BEING 30.36' SOUTH OF A-9, T1N, R10W 5. ACT 132 SURVEY: BY DENNIS A. MIDDLETON, P.S. #16049, 9-20-72, (BARRY COUNTY RECORDS) L.1, P.51, CORNER WAS NOT		
WITNESSED, BUT REFERENCED AS BEING 30.36' SOUTH OF A-9, T1N, R10W.		
6. ACT 132 SURVEY: BY DENNIS A. MIDDLETON, P.S. #16049, 12-5-72, (BARRY COUNTY RECORDS) L.1, P.62, CORNER WAS NOT		
WITNESSED, BUT REFERENCED AS BEI	NG 30.36' SOUTH OF A-9, T1N.	R10W.
7. ACT 132 SURVEY: BY WENLEY Q. SMITH, P.S. #8528, 3-18-76 (L.884, P.581), REFERENCED AS "30.36" SOUTH OF THE S.W.		
CORNER SEC. 19, T1N, R10W" NO WITNESSES GIVEN.		
8. BARRY COUNTY ROAD COMM. WITNESS CARD: NO NAME OR DATE, "2"IRON" 26" OAK NE 65.4" 18" WHITE WOOD WNW 79.9"		
the state of the s		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
FOUND 2" PIPE FILLED WITH CONCRETE, 8"+ BELOW THE SURFACE OF DOSTER LAKE. FOUND NO WITNESSES FROM THE		
ROAD COMM. (ITEM #8). MEASURED TO A.9, T1N, R10W, WHICH IS A PLAT MONUMENT AND ANOTHER PLAT MONUMENT 17' FURTHER NORTH (SHOWN ON THE PLAT OF SHANGRI-LA NO. 2, ITEM #4). DISTANCES TO BOTH FOUND PLAT MONUMENTS		
CONFIRM POSITION AS RECITED IN ITEMS #4, #5, #6, & #7.		
ACCEPTED FOUND 2" PIPE FILLED WITH CONCRETE AS BEST EVIDENCE OF CORNER POSITION.		
WE WERE UNABLE TO REMOVE FOUND PIPE. LEFT FOUND 2" PIPE FILLED WITH CONCRETE IN PLACE.		
Peer group approved Aug. 12, 1997.		
 C. Description of monument for corner and accessor 	ries established to perpetuate loc	ating the position of the corner:
2" PIPE FILLED WITH CONCRETE, 8"+ BELOW THE SURFACE OF DOSTER LAKE (2"+/- ABOVE MUCK).		
A-9, T1N, R10W (4" ROUND CONCRETE PLAT MONUMENT WITH 1/2" IRON IN CENTER) LIES N00°14'14"E 30.33"		
FOUND "PK" IN THE SOUTH SIDE OF AN 18" WILLOW N31°W 38.26"		
FOUND "PK" IN THE WEST SIDE OF A 4" ASH N10°W 40.44' FOUND "PK" IN THE NORTH SIDE OF A 12" ASH N64°E 52.00'		
FOUND "PK" IN THE NORTH SIDE OF A 12"	ASH N64'E 52.00	BRIAN
CONCRETE PLAT MONUMENT LIES N00°33' LAKE SHORE NORTH 12'+/-		REYNOLDS
LAKE SHORE EAST 10'+/-	F* ▲ÞÞÞÓVFD ÞEMONTÍ	MENTATION CORNER SURVEYOR
ETITE OFFICE COOT 10 17	P.A. 345	OF 1990
		NCOUNTY 31602
- 00	DATE APPROVED COUNTY REP	<u> </u>
$\mathcal{O}(\mathcal{X})$	L COUNTY REF.	K.V.O.
	<u>.</u> .	8-13-97
Signed by	Date_	The state of the s
Surveyor's Michigan License No31602_	FORM	MAPPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 ISED MAY 14, 1975 REVISED JANUARY, 1983 REVISED OCTOBER 1995
		•